



SOFTWARE CONTROL SERVICES (PTY) LTD

475 King's Highway, Lynnwood
P.O.Box 36675, Menlo Park
Pretoria, South Africa
0102

(t) +27 12 348 7301
(f) +27 12 348 1129
(e) techsupport@softconserv.com
www.softconserv.com

Counters - SCS_Draw How2

Version 0. 1

Prepared by: TDP

Softcon Software Control Services (Pty) Ltd.

2017-2-28

- Counter event setup.

COUNTER SETUP

GENERAL

Counter Name DT 2013/04/26 10:45:49

Minimum Now Maximum

Report Report Report

Min Tg Now Tg Max Tg

Type	System Item	Status	Value	Xref	Alarm	+-	Z1	Z2
Reader	zRD 01	Entered	1	0	0	+1	0	0
Reader	zRD 02	Entered	1	0	0	-1	0	0

- Counter name: Name the counter as you see fit.
- Maximum: Make the max to enter the facility as high as possible.
- Value: Is the trigger group you specified for the departments. Trigger 1 is the admin department. . .

Configuring the trigger group.


R...	Description
1	Admin
2	IT
3	HR
4	Sales
5	Tech
6	zTrigger GRP 6
7	zTrigger GRP 7
8	zTrigger GRP 8
9	zTrigger GRP 9

- Setup > setup editor > trigger groups

Card setup

	Status	Card	Area Group	Department	Trigger Group (V)
1	Enabled	30	admin	Admin	Admin
2	Enabled	4	admin	HR	HR
3	Enabled	8	admin	I.T	IT
4	Enabled	2	admin	Sales	Sales
5	Enabled	200	admin	Tech	Tech
6	Enabled		admin	Department 0	zTrigger GRP 0

Piant



SCS_draw


- Tools > Symbol library.

Reference	Name	File
101	Floor 01	c:\SoftWin3\bmp\floor01.bmp
102	Door latches	c:\SoftWin3\bmp\LOCK_CONT.bmp
103	Input	c:\SoftWin3\bmp\input.bmp
104	Ouput	c:\SoftWin3\bmp\output.bmp
105	floor plan	C:\softwin3\photo\floor plan.png
106	floor plan 1	C:\softwin3\photo\floor plan.png

- Name: Description of the drawing.
- File: Browse to that specific folder you have saved the drawing you've made with paint.


Pull in drawing into SCS_draw

- Edit > background



Link the counter to the drawing

- Edit > new item



- Then click on edit and then lock the drawing so that the counter can count up and down

